storm water drains. These works have since been completed and the restoration of road is in progress. The execution of electrification schemes by DESU in Rohini has, by and large, been keeping pace with the building construction and other Developmemtal activities. The Delhi Water Supply & Sewage Disposal Undertaking (DWS & SDU) has reported that the water supply position in the area under its jurisdiction is satisfatory.

Additions in Government Accommodations

4357. SHRI SUNDER SINGH BHANDARI: Will the Minister of URBAN DEVELOPMENT be pleased to state:

(a) whether allottees of type-III Government accommodation are entitled for additions/ alterations upto a maximum limit of Rs. 1500/ per annum which include laying of kota stone or Marble Stone slab in the kitchen and fixing of glazed tiles and can be taken up by concerned Service Cente of CPWD on priority basis if the allottee agrees to pay 10 percent of the cost immediately;

(b) if so, what are the reasons for denying this facility to the allottees of type-III quarters at Baba Khark Singh Marg. New Delhi on the grounds of nonavailability of funds and what are the details of the total amount allocated towards the Haveloc Square service centre under this head for the year 1994-95 and the balance available, if any, together with the details of items of works on which the allocated amount has since been exhausted;

(c) whether the allottees are communicated the positions; if not, what are the reasons therefor; and

(d) whether the main electric switch inside the quarters serviced by the said centre has since been replaced by MCB, in some quarters, if so, by when the same is likely to be replaced in all the quarters on Baba Kharak Singh Marg, New Delhi.

THE MINISTER OF STATE IN THE MINISTRY OF URBAN DEVELOPMENT (SHRI P. K. THUNGON): (a) Yes, Sir. Under the existing orders, additions/ alterations upto a maximum value of Rs. 1500/-per annum can be carried out in Type-III Government accommodation subject to availability of funds. Where, however, the allottees desire such additions/alterations to be done on priority basis, they have to bear 10 percent of the cost payable in advance.

(b) and (c) There is no instance where this facility has been denied to allottees of Baba Kharak Singh Marg Type-III quarters on grounds of non-availability of funds. There is no specific allotment of funds made to the service centres for taking up works of this nature. Since there has been no such instance, the question of communicating the position to the allottees does not arise;

(d) Yes, Sir. The work of replacement of main electric switches by MCBs in the Government quarters at Baba Kharak Singh Marg is in progress and scheduled to be completed by 31st March, 1995.

Uncovered overhead Water Tanks

4358. SHRI SUNDER SINGH BHANDARI: Will the Minister of URBAN DEVELOPMENT be pleased to state:

(a) whether it is a fact that some overhead water tanks in multi-storied Blocks of type-III quarters near Lohia Hospital at Baba Kharak Singh Marg (Phase-I), New Delhi are without proper cast iron covers, if so what are the reasons for complacency and negligence on the part of the concerned Engineers in a matter having direct bearing on the health of the resident officers of the Government and members of their families;

(b) what action is proposed to be taken in this regard;

(c) whether it is a fact that these cast iron covers have no fastening system and can be easily removed as also periodical inspections are not being done to ensure safety and proper maintenance of all such fittings, if so, what are the reasons therefor and what steps Government propose to take to ensure proper care in such matters; and

(d) what are the details of the dates on which these tanks were desilted and cleaned during the last three years and what periodicity has been fixed by the Department for this job and by when the next cleaning exercise is proposed to be completed?

THE MINISTER OF STATE IN THE MINISTRY OF URBAN DEVELOPMENT (SHRI P. K. THUNGON): (a) No, Sir. All overhead water tanks are covered with proper cast iron covers/RCC covers.

(b) Does not arise in view of reply to (a) above.

(c) Yes, these cast iron coveres do not have locking system. However, the roofs are accessible only through trap door with the help of a ladder. Periodical inspections are being done by site staff and all fittings are being checked.

(d) The tanks were cleaned and chemically treated in May, 1992, June, 1993 and April, 1994.

The tanks are usually cleaned once a year. However, in a specific cases of complaints the tanks are cleaned more often by Departmental labour.

Dilapidated Condition of Over Head Water Tanks at BKS Marg

4359. SHRI SUNDER SINGH BHANDARI: Will the Minister of URBAN DEVELOPMENT be pleased to state:

(a) whether the residents as also the Residents Welfare Association of multistoried type-III quarters at BKS Marg (Phase I), New Delhi have been lodging complaints in person as well as in writing to the Executive Engineers of "H" Division for the last 2-3 years about the dilapidated conditions of some of the over-head water tanks which, as per complaints, are likely to collapse or crash down any day due to weight of water or under the impact of earth tremors experienced in Delhi frequently;

(b) if so, what are the date-wise details of complaints and action taken thereon so far; and

(c) whether these tanks have ever been inspected by the senior-engineers of their own to ensure their safety; if so, what are the details thereof and what are the details of the arrangements made for equitable distribution of water to all the said quarters?

THE MINISTER OF STATE IN THE MINISTRY OF URBAN DEVELOPMENT (SHRI P. K. THUNGON): (a) and (b) No such complaints regarding dilapidated condition of overhead tanks have been received from Residents/Associaiton of Type-III quarters at BKS Marg (Phase-I) by Executive Engineer 'H' Division. However, periodic inspection is being done by field staff and if any deterioration is noticed, the action to repair the same, is being taken. Presently, no tank of this colony has been declared dangerous.

(c) The Superintending Engineers inspect the building during their routine inspections. However, specific detailed inspections are carried out in case some damage is noticed by Field Staff or reported by Residents. Regarding equitable distribution of water, first the water is supplied to individual overhead tank of the blocks from Central overhead tanks. From individual overhead tanks of the block the water is supplied to all the quaters of the block and water distribution is generally equitable.

नेहरू रोजगार योजना के कार्यनिष्पादन की समीक्षा किया जाना

4360. **श्री दिलीप सिंह जूदेव:** क्या **शहरी विकास** मंत्री यह बताने की कृपा करेंगे कि:

(क) क्या सरकार ने पिछले तीन वर्षों के दौरान मध्य प्रदेश में नेहरू रोजगार योजना के कार्य-निष्पादन की समीक्षा की है;

(ख) यदि हां, तो तत्संबंधी ब्यौरा क्या है;

(ग) क्या इसके कार्यान्वयन में कुछ कमियां पाई गई हैं;

(घ) यदि हां, तो इसके क्या कारण हैं;

(ङ) उक्त अवधि के दौरान इस योजना पर कितनी धनराशि खर्च की गई है; और

(च) इस योजना के अंतर्गत बैंकों से ऋण प्राप्त करने की प्रक्रिया को सरल बनाने हेतु क्या कदम उठाये गये हैं?

शहरी विकास मंत्रालय में राज्य मंत्री (श्री पी. के. थुंगन): (क) और (ख) मध्य प्रदेश में नेहरू योजना के कार्यान्वयन की फील्ड दौरों सहित दिल्ली में बैठकों और राज्य मुख्यालयों पर परिचर्चा के जरिए आवर्ती आधार पर समीक्षा की जाती है ताकि लक्ष्यों की प्राप्ति का मूल्यांकन किया जा सके और ऐसी समीक्षाओं के दौरान पायी गयी कमियों को, यदि कोई हों, दूर करने के उपाय किए जा सकें। गत समीक्षा जुलाई, 1993 में की गयी थी।